

Ref No: 4885

Date: 19-05-17

Building Safety Certificate

This is to certify that inspection of Trinity Global School was conducted by one of our empaneled structural engineer Mr Shailendra Kumar (Empanelment No: SE/06/15) and findings are

- The structure of the school is as per the Building codes (Code: 1893:2002, IS:13920:1993, SP:16)
- Building of the school is Earthquake resistant (Code: 1893:2002)

  
Signature With Seal :

Name : सत्येन्द्र कुमार सिंह  
उप निदेशक, शहरी योजना  
पटना नगर निगम, पटना

Designation :

To,

Trinity Global School

Jhali, New Transport Nagar,

Patna - 800007